

CENTRAL ADAPTORS PLASMA CUTTING

CENTRAL ADAPTORS TIG WELDING




FY0022	Plasma conn. (f)	1
FY0023	Plasma conn. (m) 5pin	1
PT0024	kit Plasma conn.	1

FY0002	female Tig conn.	1
TT0018	Tig kit	1
TT0108	Tig adaptor	1

BW0018	Euro nut plastic	10
BW0147	cable Support	10
BW0148	Tig-Plasma box	10
BW0162	joint	10
BW0174	nut	1
BW0214	washer	10
BW0265	ring	10
BW0328	back box	1
BW0329	cable protection	1
BX0044	Plasma pin (m) 5mm	10
BX0046	Plasma pin (m) 8mm	10
BX0047	Plasma pin (m)	10
BX0240	contact (f)	10
CV0053	electrode wrench	1
EA0018	screw M4x6	50
EA0032	washer	50
EA0064	screw 3.9x16	50
EA0206	o ring Ø 7x2 nbr	10
EA0235	screw	10
EA0254	pin extractor	1
EA0285	hose clamp Ø 10.5	10

EA0374	spring	1
FA3020	quick connector	10
FA5019	reduction M14x1 - 1/4G	1
FA5029	reduction 3/8G - 1/4G	1
FA5105	reduction M12x1 - 1/4G	1
FE1132	gas hose+quick conn.	1
FE1133	gas hose+nut 1/4G	1
FE1134	connector 3/8 G	1
FE1135	connector M12x1	1
FH0320	insulator	10
FY0002	female Tig conn.	1
FY0018	Plasma conn. (m)	1
FY0022	Plasma conn. (f)	1
FY0023	Plasma conn. (m) 5pin	1
FY0024	adaptor	1
FY0040	Tig connector (m)	1
FY0041	Plasma connector (m)	1
PT0024	kit Plasma conn.	1
TT0018	Tig kit	1
TT0108	Tig adaptor	1

CENTRAL ADAPTORS PLASMA CUTTING



CENTRAL ADAPTORS TIG WELDING

